


Firmware Release Note



The version (s) indicated here above has (have) been tested and validated by the Technical Support Department.

Technical Notes

Version 4.20

- Evolution: Payload ID management for SDI outputs
- Correction: the layer name in the OSD becomes W1 instead of PIP1
- Correction: Problem of frame capture size when switching capture source from RCS
- · Correction: Automatic exit of menu "Motion correction" doesn't work when switching to a non-interlaced input
- Correction: The logo Chroma-key grabber position doesn't change on output 2
- Correction: When changing the HV size of a PIP, the H size suddenly goes to 0
- Correction: Strobbing effect for sources whose rate is really close to the output rate
- Correction: Embed the payload ID of HDTV format in the SDI data output streams
- Correction: The tolerance setting of logo capture keying doesn't work
- Correction: When switching the logo capture source from RCS, the grabber doesn't disappear from the previous capture source
- Correction: Presets layouts are not working in Quadra vision mode

 $\begin{array}{lll} \mbox{MM:} & \mbox{K} = \mbox{FF00} \\ \mbox{MF:} & \mbox{K} = \mbox{54F6} \\ \mbox{CA:} & \mbox{V} = \mbox{0037} \\ \mbox{FA:} & \mbox{V} = \mbox{0044} \\ \mbox{TH:} & \mbox{V} = \mbox{0037} \\ \mbox{CS:} & \mbox{V} = \mbox{0009} \end{array}$

